
WIRING DIAGRAM FOR FOLDING/SWING MOTOR WITH M1 CONTROL PANEL



Remote Control Programming Method :

1) To Program - Press the " *Program Button* " switch x1 time ,the GREEN LED will ON , Then Press the Remote Control (any button), GREEN LED will Blinking

2) To Erase - Press and hold the " *Program Button* " switch , 5 -6 second until the LED blinking.





plate. Then, Slot in & secure the C-channel



Measure and install the C-channel base plate. Then, Slot in & secure the C-channel